

**Appendix B**  
**Photograph Log**



Photo 1. Tansill Residence on Parcel 349.



Photo 4. Partially filled 55-gallon plastic drum containing used oil.



Photo 2. Pole mounted transformer observed on Parcel 349; Non-PCB blue placard observed.



Photo 5. Stored new petroleum products observed in shed west of Tansill Residence on Parcel 349.



Photo 3. Private well associated with Parcel 349, located within a small well house.



Photo 6. Plastic gasoline containers (< 5-gallons) observed near the exterior perimeter of the outbuildings on Parcel 349.



**Photo 7.** Lead-acid battery observed on ground surface on Parcel 349.



**Photo 10.** Discarded refrigerator observed at western property boundary of Parcel 235.



**Photo 8.** Sewer easement access looking west toward Rose Lane.



**Photo 11.** Example of area of mounded soil with associated automotive/non-household waste.



**Photo 9.** Example of discarded household waste observed along sewer easement.



**Photo 12.** Discarded tires noted in multiple locations throughout the study area.



**Photo 13.** Large pile of waste with electrical construction materials observed on Parcel 235.



**Photo 16.** Heavily overgrown vegetation in the vicinity of the former dwelling on Parcel 235.



**Photo 14.** Representative transite pipe observed in multiple location onsite.



**Photo 17.** Remnant possible structure observed near northeastern boundary of Parcel 235.



**Photo 15.** Collapsed small structure observed on Parcel 235 between Parcel 349 and the railroad tracks.



**Photo 18.** Typical metal debris observed on Parcel 235.



Photo 19. Area to the west of Parcel 235 observed with approximately 20 tires.



Photo 22. Looking southeast towards water tower adjacent to the south of Parcel 384.



Photo 20. Out of service, railroad track that form the eastern boundary of the study area. Note Savage Stone quarry on left, looking south.



Photo 23. Stormwater retention pond observed in the southeast corner of Parcel 235, associated with the former Laurel Lumber reclaimed mine located southwest of Parcel 235.



Photo 21. Typical open wooded land of Parcel 384.



Photo 24. Possible building remnants/piping observed near the northern boundary of Parcel B.